

COPIES RECEIVED		
TRIBUTION		
FE		
OFFICE		
RATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT -- (FORM C-101) FOR SUCH PROPOSALS.)

☐ WELL ☒ CAS WELL ☐ OTHER

Name of Operator
 Mesa Petroleum Company

Address of Operator
 1000 Vaughn Building / Midland, Texas 79701

Location of Well
 T11N R10E S14
 K 1980 South 1980
 West LINE, SECTION 14 TOWNSHIP 16S RANGE 35E

30. Indicate Type of Lease
 State ☒ Fee ☐

31. State Oil & Gas Lease No.
 K-5953

7. Unit Agreement Name

8. Farm or Lease Name

Monsanto State

9. Well No.

1

10. Field and Pool, or Wildcat

Townsend, Morrow

12. County

Lea

15. Elevation (Show whether DF, RT, GR, etc.)

GL 3980 RKB 3993

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

☐ REMEDIAL WORK	☐ PLUG AND ABANDON	☐ REMEDIAL WORK	☐ ALTERING CASING
☐ PARTIAL ABANDON	☐ CHANGE PLANS	☐ COMMENCE DRILLING OPS.	☐ PLUG AND ABANDONMENT
☐ ALTER CASING	☐	☐ CASING TEST AND CEMENT JOBS	☒ OTHER Repair Casing Leak

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations.) SEE RULE 1103.

Commenced repair operations on 9-19-79 to repair suspected hole in 4-1/2" casing. Discovered holes between 5508'-5523' and 5773'-5789'. Set retainer at 5666'. Cemented with 900 sx Class "H" + 3/4% CFR-2 + 1/4# Flocele + 2% Gel on 9-20-79 to seal holes. WOC total of 72 hours. Casing and cement tested to 1000 psi - ok, on 9-24-79. Tagged cmt @ 3707' (1959' of fill). Drilled cmt. to top of retainer. Tested casing to 1000 psi - 30 min - ok. Drilled retainer (had 3' void below retainer) and cement to 5802'. Tested casing to 1000 psi. Ran tbq, then engaged packer @ 11,799'. Swabbed well to kick off. Turned Morrow zone to sales line on 10-2-79. Wolfcamp zone (Shoe Bar, North) is shut in (behind tbq).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

R. F. Martin

TITLE Regulatory Coordinator

DATE 10-3-79

Orig. Signed

XC: NMOCD (3), TLS, JWC, Title, WI Owners, D&M

Dist 1. Supv.

OCT - 5 1979

RECEIVED

OCT - 11

O.C.D. HOBBS, OFFICE