TRIBUTION	NEW MEXICO OIL CONSI	ERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65	
U.S.G.S.			5a. Indicate Type of Lease	
LAND OFFICE			State Fee K	
OPERATOR			5. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PRO USE "APPLICATI	Y NOTICES AND REPORTS ON POSALS TO DRILL OR TO DEEPEN OR PLUE BA	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	7. Unit Agreement Name	
L. OIL X GAS WELL	0THEP-		7. Omt Agreement Nume	
2. Name of Operator	OTHER-		8. Farm or Lease Name	
Mesa Petroleum C	West Knowles			
3. Address of Operator	9. Well No.			
904 Gihls Tower	5			
4. Location of Well			10. Field and Pool, or Wildcat	
HNIT LETTER H 19	180 FEET FROM THE North	LINE AND 660 FEET PRO	West Knowles Drinkard	
	34 TOWNSHIP 16S			
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
		5 RKB	Lea	
	Appropriate Box To Indicate N	ature of Notice. Report or O	ther Data	
NOTICE OF IN		SUBSEQUEN	T REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASTNG	CHANGE PLANS	CASING TEST AND CEMENT JOB		
		OTHER		
OTHER				
work) SEE RULE 1103.			g estimated date of starting any proposed	
Spudded 17½" hole on 5-29-75. Drilled to 360'. Ran 10 jts 13 3/8" 54# K-55 ST&C casing with guide shoe to 360'. Installed one centralizer on top of first joint. Cemented with 375 sx Class "H" with 2% cc. PD @ 10:30 PM. Circ. out 5 sx cement. WOC 24 hrs. Tested csg to 750 psi - 30 min - OK.				
Drilled 12¼" hole to used casing to 4200'	4200', on 6-4-75. Ran with guide shoe and ins	118 jts 9 5/8" 36-40# K ert float. Installed c	entralizer on	
11:45 AM. 6-5-75. W	Cemented with 250 sack OC 24 hrs. Tested csg t y - 2660'. GIH w/8 3/4"	o 1000 psi – 30 min – O	K. Top of cement	
While attempting to Subsequent surveys i	ream thru tight spots, s ndicated separation was	uspect casing parted or in joint at 2095'. GIH	w/8½" drilling assembly	
and drilled collar a 500 sx Class "C" wit	nd shoe. Unable to get h 8# salt and 2% cc whil	back down. Cemented c e taking returns out br	asing separation with adenhead. WOC 24 hrs.	
After drilling out cement in lower 9 5/8", unable to get back into same. Ran casing alignment tool and cemented with 100 sx class "C" and 8# salt + 2%cc, followed by 150 sx				
alignment tool and c	emented with 100 sx class 1t. WOC 24 hrs. Drille	$d$ out with $8\frac{1}{2}$ bit but	umable to get into	
bottom casing with e Drilling.	ase. Tested csg to 1000	psi - 30 min - OK. Re	duced hole to 7 7/8" -	
18. I hereby certify that the information	above is true and complete to the best of	of my knowledge and belief.		

\$16NED	Michael Brig. Houston	TITLE Division Engineer	DATE June 17, 1975
<del>,</del>	Geologia		
A BREAVED BY	•	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY:

XC- 3 NIMOLE, 1-JIF, 1-LME, 1-W.I. OWNERS, 1-10+M, 1-MAM, 1-MEC, 1-MAH