Submit 3 Copies to Appropriate District Office	State of New Me Energy, Minerals and Natural Re		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hotbs, NM 88240	OIL CONSERVATIO P.O. Box 208	18	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico REVISED	87504-2088	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztoc, NM 87410			6. State Oil & Gas Lease No. L-990
SUNDRY NO	TICES AND REPORTS ON WEL	LS	
(DO NOT USE THIS FORM FOR PE DIFFERENT RESE (FORM	COPOSALS TO DRILL OR TO DEEPEN ERVOIR. USE "APPLICATION FOR PER C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Leuse Name or Unit Agreement Name
1. Type of Well: OIL WELL X WELL) OTHER	· · ·	West Knowles Unit
2 Name of Operator	:	· · · · · · · · · · · · · · · · · · ·	8. Well No.
Santa Fe Exploration 3. Address of Operator	Company		No. 6 9. Pool name or Wildcat
P. O. Box 1136. Rosi	ell. New Mexico 88202-	1136	West Knowles Drinkard
4. Well Location Unit Letter			
Section 35	Township 16-S R	mge37-Е	NMPM Lea County
	10, Elevation (Show whether	DF, RKB, RT, GR, etc.)	
n. Check	Appropriate Box to Indicate 1	Nature of Notice R	enort or Other Data
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLING	
		CASING TEST AND CE	
OTHER:		OTHER:	
12 Deambe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. Begin operations 6-22-92: RUPU. POH with rods and pump. TOH with tubing. TIH with hydrotested tbg. and packer. Set packer to isolate existing recorded perfs & swabbed below to check for fluid entry. Recovered 75 BW and 0 BO with a slight amount of gas. Fluid level from 3000' to 3700' FS. RU wireline and set bridge plug at & 200'. Tag plug and pull out of hole. Pressure up on casing and would not hold. RU wireline and run casing inspection log. Log showed possible bad collar at 5200' and possible bad joints from 6130' to 6300'. Load hole and run cement bond log. Top of cement found at approx. 6800'. No bonding above 6800'. TIH with tubing and packer to locate casing leak. Had leak-off from 5200' to 5950'. TOH with tubing and packer to check packer elements. 6-29-92: SD and await further instructions. RD & MOPU.			
	is and complete to the best of my knowledge and		
SIGNATURE <u>FACHAGO</u> CAL	•	<u>Petroleum Enc</u>	(505)
	<u>Gilliland</u>		TELETHONE NO. 623-2733
2 A.D.	igned by Rantz logist		JUL 2 3 '92
APTROVED BY	tu, i i i i i i i i i i i i i i i i i i i		DATE
CONDITIONS OF APPROVAL, IF ANY:			
· · ·			

CD HORRS OTT

JUL 2 2 1992

RECEIVED

¢