

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form Approved.  
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well

2. NAME OF OPERATOR  
*Continental Oil Company*

3. ADDRESS OF OPERATOR  
*Box 460 Hobbs, N.M. 88240*

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: *660' FSL + 1980' FEL*

AT TOP PROD. INTERVAL: *Same*

AT TOTAL DEPTH: *Same*

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

(other) *Set 8 3/8" Surface CSG.*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

*Spudded 8-21-77 and DRLD 12 1/4" Hole to 1171'  
Ran 8 3/8" 28# H-40 CSG Set AT 1171' CMTD  
w/586 SX Class "C" CMT and 2% CACL<sub>2</sub>. CMT  
Circ, WOC 18 Hrs, Tested to 500 PSI, Hold  
OK. DRLD Ahead with 7 3/8" Hole.*

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED *Bruce H. Lee*

TITLE *Supervisor*

DATE *August 29, 1977*

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD  
AUG 29 1977

U.S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

USGS(5), File

\*See Instructions on Reverse Side

RECEIVED  
AUG 1 1977  
OIL CONSERVATION COMM.  
HOBBS, N. M.