

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 3819	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Hexagon Oil and Gas Inc.		8. Farm or Lease Name Sombbrero MS State
3. Address of Operator 411 W. 7th St., 905 Neil P. Anderson Bldg., Ft. Worth, Tx. 76102		9. Well No. 2
4. Location of Well UNIT LETTER C 550 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 16S RANGE 33E NMPM.		10. Field and Pool, or WHdcat Kemnitz-Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4194' GL; 4208' KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

From 9-1-81 through 9-30-81: On 9-3-81 washed over @ 4626' and recovered 94' of 4 1/2" casing. On 9-4-81 left 1 joint wash pipe & wash over shoe in hole. Cut 4 1/2" csg. @ 4627'. Couldn't jar fish loose. Re-cut csg. @ 4619'. Got over fish & continued washing over pipe. On 9-11-81, cut csg @ 4630' and recovered 3.10' of csg. On 9-19-81 washed over & cut csg @ 4748'. Recovered 76' of 4 1/2" csg. Continued washing over csg. Washed over 4 1/2" csg to 5149' by 9-30-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John G. Burke /John G. Burke TITLE Engineer DATE 10-2-81

APPROVED BY _____ TITLE _____ DATE NOV 10 1981
CONDITIONS OF APPROVAL, IF ANY: