

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 1472

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- PxA	7. Unit Agreement Name
Name of Operator Amoco Production Company	8. Farm or Lease Name State Ho Com
Address of Operator P. O. Box 68 Hobbs, NM 88240	9. Well No. 1
Location of Well UNIT LETTER K, 2310 FEET FROM THE South LINE AND 1942 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 16-S RANGE 35-E NMPM.	10. Field and Pool, or WHdcat Wildcat Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 4032.7' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PxA by spot cementing with 100' plugs at the following intervals:

12425-12525 with 40 sacks of class H
11770-11870 with 40 sacks of class H
10680-10780 with 40 sacks of class H
9740- 9840 with 40 sacks of class H
6170- 6270 with 40 sacks of class H

Spotted 100' plug 50' in (4930) and 50' out (5030) of intermediate casing set at 4980.

Spotted 100' plug 100' inside intermediate casing from 1865'-1965'.

Spotted 10 sacks of cement at surface

Erected PxA marker. Location to be cleaned and leveled.

0+4 NMCD, H 1-Hou 1-W. Stafford, Hou 1-GPM 1-Susp

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Randolph TITLE Assist. Admin. Analyst DATE September 15, 198

APPROVED BY Eddie W. [Signature] TITLE OIL & GAS INSPECTOR DATE SEP 15 1982

CONDITIONS OF APPROVAL, IF ANY: