

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

P. O. BOX 1980  
HOBBS, NEW MEXICO 88401

# SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR  
Lejas Oil Operators
3. ADDRESS OF OPERATOR  
Box 58, Midland, Texas 79708
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
369'
- AT SURFACE: 3658'
- AT TOP PROD. INTERVAL: 3689'
- AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
- FRACTURE TREAT ☐
- SHOOT OR ACIDIZE ☐
- REPAIR WELL ☐
- PULL OR ALTER CASING ☐
- MULTIPLE COMPLETE ☐
- CHANGE ZONES ☐
- ABANDON\* ☐
- (other) running 8 5/8" casing

SUBSEQUENT REPORT OF:

RECEIVED

AUG 25 1981

U.S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

(NOTE: Report results of multiple completion or zone change on Form 9-330)

RECEIVED  
AUG 21 1981

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4-7-81

bottom of pipe set at 394'. Ran 8 5/8" 24# (354') J-55 ST&C casing. 175 sacks of Class "C" with 2% Cal. Chloride and cement did circulate out 25 sacks.

Subsurface Safety Valve: Manu. and Type Halliburton xxx float Set @ 3949 Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *JML* TITLE Agent DATE 8-20-81

ACCEPTED FOR RECORD  
ROGER A. CHAPMAN

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: TITLE DATE

AUG 24 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side