

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
LG3657

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Argee Oil Company

Address of Operator
810 C & K Petroleum Bldg., Midland, Texas 79701

Location of Well
UNIT LETTER I 660 FEET FROM THE East 1980
South 16 LINE, SECTION 15-S RANGE 36-E TOWNSHIP NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Diane State

9. Well No.
1

10. Field and Pool, or Wildcat
Caudill Permo Penn

15. Elevation (Show whether DF, RT, GR, etc.)
3902 Ground

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded well at 12:00 noon, 8-26-81. Drilled 17½" hole to 350'. Ran 13 3/8" 48#/ft. casing to 350' and cemented to surface with 370 sacks Class C with 2% CaCl₂. Drilled 11" hole to 1553' and drill string stuck. Worked 7 days attempting to fish 11 drill collars unsuccessfully. Well was plugged and abandoned by spotting 150 sack plug on top of fish at 1205', 75 sack plug from 250'-400' (across 8 5/8" casing shoe) and 10 sack plug at surface and cut 13 3/8" casing off 5' below ground level. Plugging complete 9-6-81.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Engineer DATE 9-15-81

APPROVED BY David R. Cotnam TITLE OIL & GAS INSPECTOR DATE JUL 29 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 28 1981

DR. CORINNE A. DILLON