NO. OF CUPIES ALCEIVED DISTRIBUTION SANTA FE FILE U.S.G.S.	NEW MEXICO OIL CONS	ERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State Fiee
LAND OFFICE OPERATOR			State   File     5. State   Oil & Gas   Lease   No.     LG-1551   & LG-1641
SUNDRY NOTICES AND REPORTS ON WELLS			
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOBALS.)			7. Unit Agreement Nume
UIL GAB X OTHER-			
Great Western Drilling Company			8. Form or Lease Hame State 12
Э, Address of Operator			9. Well No.
P.O. Box 1659, Midland, TX 79702			10. Field and Pool, or Wildcat
UNIT LETTER J 1980 FLET FROM THE South LINE AND 1980 FLET FROM			Sombrero Morrow
THE East LINE, SECTION 12 TOWNSHIP 16-S RANGE 33-E			. MARINA MARINA
	15. Elevation (Show whether i		12. County
	4,183.1'KBM, 4,		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: 5085EQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CABING
PULI. OR ALTER CABING	CHANGE PLANS	GASING TEST AND CEMENT JOB	
0THEN		UTHER Process of	completion  x
17. Describe proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting thy proposed			
work) SEE HULE 1103. $\frac{6}{5}/84$ : Ran cement bond log to 7,330', could not go any deeper. Tied into open hole logs. Pulled bond log, found top of cement @ 4,295' on outside of $5\frac{1}{2}$ " csg. Found good cement bond from 7,330' to 4,295' to top of cement. DV tool @ 7,561' - not logged.			
<u>6/6/84</u> : Rigged up pulling unit. Ran 4-5/8" bit on 2-3/8" OD, tbg to 7,549'.			
$\frac{6}{7}$ 84: Rigged up reverse unit & displaced mud in hole w/fresh water. Washed from 7,549' to 7,561', recovered heavy mud. POH w/4-5/8" bit. T.I.H. w/3-3/4" bit to top of DV tool @ 7,561'. Washed to top of opening bomb @ 7,562'. Turned thg w/tongs. Circ. bottoms up - recovered cuttings from bomb & small amount of mud. Pulled 1 jt thg & shut down.			
on 2-3/8" OD, tbg. Push tool. Drilled out plugs	ned plug to DV tool @ 7,5 & DV tool. Pressure to	561', set down on pl ested csg & tool to	. w/4-5/8" bit, 3 4-1/8" DC ug & closed ports on DV 2,100 psi for 30 min, held. ement). Circ. hole clean
6/9/84: Drlg cement to top of float collar @ 13,198.46', 499.85' of cement, good hard cement   except the last 30' was chalky. Circ. hole clean & shut down.   1b. I hereby certify that the information above is true and complete to the best of my knowledge and belief. (Cont.)			
SIGNED M. H. Muga	D TITLE AS	as't. to Gen. Supt.	DATE 7-3-84
			JUL 1 0 1984