



INCLINATION REPORT

OPERATOR:

LOCATION:

Maralo, Inc.

P.O. Box 832

Midland, Texas 79701

State "10" #1 Lea County, NM

DEPTH FEET	INCLINATION DEGREES	DEPTH FEET	INCLINATION DEGREES	DEPTH FEET	INCLINATION DEGREES
	. 1/2	6680	3/4		
495	1/2		3/4		
990	3/4	7180	1 1/4		
1200	3/4	7675			
1639	3/4	8168 .	1/4		
1950	3/4	8300	1/4		
2434	3/4	8818	3/4		
2908	1/2				
3100	3/4				
3550	3/4				
3916	1/4				
4030	1/4		-		
4523	1/4				
5020	1/2.				
5516	1/2		•		
5979	1/4				
6478	3/4				_

COUNTY OF MIDLAND STATE OF TEXAS

The undersigned states that he has knowledge of the facts and matter herein set forth and that the same are true and correct.

Grimes, President

SUBSCRIBED AND SWORN TO BEFORE ME THIS 20 day of

My commission expires:,

FM 1788 = 2 ML, SOUTH 1-20, ROUTE 6, BOX 833 • MIDLAND, TEXAS 79701 • PHONE: (915) 563-0221