WILLBROS DRILLING, INC.



INCLINATION REPORT

OPERATOR: Maralo, Inc.

. P.O. Box 832

Midland, Texas 79701

LOCATION: State "10" #2

Lea County, NM

DEPTH FEET	INCLINATION DEGREES	DEPTH FEET	INCLINATION DEGREES	DEPTH FEET	INCLINATION DEGREES
405 901 1400 1867 2054 2552 2915 3168 3490 3836 4000 4496	DEGREES 1/4 1/4 1/4 3/4 1/2 1 1 11/4 3/4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	6290 6655 7042 7512 8010 8485 8800 9014 9514 10,000 10,200	1½ 1½ 1½ 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		DEGINEES
4943 5350 5620 5914 5991	1½ 1 3/4 1½ 1½ 1½ 1½				

COUNTY OF MIDLAND STATE OF TEXAS

The undersigned states that he has knowledge of the facts and matter herein set forth and that the same are true and correct.

SUBSCRIBED AND SWORN TO BEFORE ME THIS 15th day of

1-20. ROUTE €. BOX 833 • MIDLAND, TEXAS 79701 • PHONE: (915) 563-0221 SIDIARY OF WILLEROS ENERGY SERVICES COMPANY