

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 3726	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Yates Petroleum Corporation		
3. Address of Operator		9. Well No.
105 South 4th St., Artesia, NM 88210		1
4. Location of Well		10. Field and Pool, or WHdcat
UNIT LETTER <u>E</u> , <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM		<u>Wildcat</u>
THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>15S</u> RANGE <u>35E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4019' GR		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Spud, Set Surface pipe</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Spudded 26" hole at 1:15 PM 7-31-86 with Frank's Rat Hole. Set 40' of 20" conductor pipe. Notified June Goble with NMOCD, Hobbs, NM, of spud. Moved in rotary tools and resumed drilling 9:30 PM 8-6-86. Ran 12 jts 13-3/8" 61# J-55 casing, set 475'. 1-Texas Pattern Notched Guide shoe set 475'. Insert float set 435'. Cemented w/450 sx Class "C" w/2% CaCl2. Compressive strength of cement 1250 psi in 12 hrs. PD 5:15 PM 8-7-86. Bumped plug to 2400 psi, released pressure and float held okay. Cement circulated 100 sx to pit. WOC. Drilled out 6:30 PM 8-8-86. WOC 25 hrs 15 mins. Cut off and welded on flow nipple. Reduced hole to 11". Drilled plug and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Supervisor

DATE 8-11-86

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE AUG 13 1986

CONDITIONS OF APPROVAL, IF ANY: