STATE OF NEW MEXICO

• · · · · · · · · · · · · · · · · · · ·
ENERGY AND MINERALS DEPARTMENT
40 9" (00:E6 \$E,E.TE

	_	-
(04-66 35.6.469	1	
DISTRIBUTION		
SANTA FE		
rice		
U.S.G.S.		
LAND OFFICE		

OIL CONSERVATION DIVISION

<u></u>	OIL CONSER			Farm 0-103
DISTRIBUTION	P O BOX 2088 Figure 13.1		Routist 11-1-13	
SANTA FE	SANTA FE, NEW MEXICO 87501 AI		API #	30-025-30175
FILE				cute Type of Lease
U.S.G.S.			1 -	
LAND OFFICE			Stat	e XX Fee
OPERATOR			5. State	OI, & Gas Lease No.
	:		LG	3345
				mmmmm
SUNDR'	Y NOTICES AND REPORTS	ON WELLS		
IDO NOT USE THIS FORM FOR PROI USE "*APPLICATI	POSALS TO ORILL OF TO DECPEN OR PLION FOR PLUM FOR PLANT -1" (FORM C-101) FOR	UG BACK TO A DIFFERENT RESERVOIR SUCH PROPOSALS.)	· /////	
11.			7. Unit	Agreement Name
an (
week X week	OTHER-			
2. Name of Operator			8. Foorm	or Lease Name
Yates Petroleum Co	ornoration		Hoov	ver ADR State
			9. Well	
J. Address of Operator			I ' '_	140.
105 South 4th St.	, Artesia, NM 88210		5	
4. Location of Well			10. Fie	ld and Pool, or WHdcat
. –		•	l	
L 150	00 FEET FROM THE Sout	h LINE AND 990	FEET FROM Unde	esignated Grayburg
l Work	1	170 225	[[]]	VIIIIIIIIIIII
THE WEST LINE, SECTIO	n 1 TOWNSHIP	1/5 RANGE 33E	имрм. []]]	
·				
	15. Elevation (Show whe	ther DF, RT, GR, etc.)	12. Coi	mty ///////
		4150.3' GR	Lea	
	7////	4130.3 GK	Ties	
Check A	Appropriate Box To Indicat	e Nature of Notice, Repo	rt or Other Dat	а
	• •			
NOTICE OF IN	FENTION TO:	2082	EQUENT REPO	RI OF:
		1		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
=	•	COMMENCE DRILLING OPHS.	<u>লি</u>	
TEMPORARILY ABANDON			₹ 7	PLUG AND ASANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	LOT THEMS ON TEST BUILDS		
		OTHER		
	. 1	<u> </u>		
OTHER				
17. Describe Proposed or Completed Op	erations (Clearly state all pertinent	details, and give pertinent dates,	including estimate	a date of starting any proposea
work) SEE RULE 1103.				
C11-1 10 1//H b-1	le at 9:15 AM 1-16-88.	Dom 26 inimes 0 5/	OH 2/# T EE	
•		-		•
set 1520'. Guide s	shoe set 1520', float	collar set 1477'. C	emented $w/57$	⁷ 5 sx
Pacesetter Lite "C	" + 1/4#/sx Celloseal	(vield 1.8, weight 1	2.4) . Taile	d in w/
	ith 2% CaCl (yield 1.3			
Bumped plug to 1000	O psi, released pressu	ire and float held ok	ay. Circula	ited 75 sx
to pit.				
-	w 1 20 00 TIOC 22 have	and 15 minutes. MT	+	t- 1000
	M 1-20-88. WOC 33 hrs			to 1000 psi
tor 10 minutes, OK	• Reduced hole to $7-7$	//8". Resumed drilli	ng.	
·				
·				
·				
48. I hereby certify that the information	shove is true and complete to the b	est of my knowledge and belief.		
.8. I hereby certify that the information	above is true and complete to the b	est of my knowledge and belief.		
.8. I hereby certify that the information	above is true and complete to the b			1.00.00
.8. I hereby certify that the information	above is true and complete to the bo	Production Supervis	OT DAT	1-22-88
18. I hereby certify that the information	Above is true and complete to the b		OT DAT	,1-22-88
18. I hereby certify that the information	above is true and complete to the b		OT DAT	,1-22-88
* 164 to Santa Don	lless TITLE_		OT DAT	
ORIGINAL SIGNED BY	Y JERRY SEXTON		OT DAT	1-22-88

TANKS OF THE STATE OF THE STATE