



## BRIDGE OIL (U.S.A.) INC.

### Julia Culp #2 DST Tests

Unit H; Section 34, T15S, R35E, Lea County, New Mexico

- DST #1 11080-11127 Open 10, Close 30, Open 95, Close 180, IF 52 psig, ISIP - 511 psi, FF - 52 psi, FST - 1128 psi, BHT 153°F, Rec 60' drlg mud.
- DST #2 11500-11568 Open 10, Close 30, Open 90, Close 180, IF - 400-377 psig, ISIP - 3755 psig, FF - 335-398 psig, FSI - 3481 psig, GTS after 102 min. Recover 1000' GCWC, 130' GCMD.
- DST #3 11690-11744 Open 10, Close 30, Open 60, Close 120, IF - 503 psig, ISIP - 3507 psig, FF - 529-503 psig, FSI - 3820 psig, BHT - 160°F, GTS - 137 min. Recover 1045' G&OCWC, 155' G&OCDM, BHT - 160°F.
- DST #4 11850-11950 Pkr. failure.
- DST #5 13386-13471 Open 10, Close 30, Open 120, Close 240, IF - 1161 psig, ISI - 6229 psig, FF - 1214 psig, FSI - 6703 psig, GTS - 58 min., FARO - 150 MCFPD. Recover 3000' GCWC, 50' GCDM, BHT - 185°F.
- DST #6 13865-13900 open 10, Close 30, Open 310, IF - 1732 psig, ISI - 5216 psi, FF - 3296 psig. Recover 3500' WC, 270' WCDM, 3500' XW, BHT - 212°F.

DBM/tsc  
T9007025.DBM