

9. If non-productive plug in accordance w/ State regulations, cover pits and restore as near as possible to original condition.
10. This application submitted under Case No. 9807, Order No. R-9046.
11. The surface location is 2522' from the North line and 2172' from the West line of Sec 33, T 16S, R 38E of Lea County, NM.