Submit 3 Copies to Appropriate District Office

ATTROVED BY ---

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		ADTUICION	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30 025 31365
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Diawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE TEE FEE	
DISTRICT III 1000 RIO BISZON Rd., AZIEC, NM 87410			6. State Oil & Gas Lease No. B 7896
	TERRORITO ON WEL		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Lovington San Andres Unit
I. Type of Well: OIL XXX WELL [OTIER		8. Well No.
2 Name of Operator	CORPORATION		71
GREENHILL PETROLEUM CORPORATION 3. Address of Operator 11490 Westheimer, Suite 200, Houston, Texas 77077			9. Pool name or Wildcat Lovington Grayburg San Andres
4. Well Location	362 Feet From The South		5 Feet From The East Line
	166	37F	NMPM Lea County
Section 31 Township 16S Range 3/E NMPM 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3814 GR			
Charle Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
II. Check	TENTION TO:	SUE	SEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING			
PERFORM REMEDIAL WORK			
TEMPOPARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN CASING TEST AND CEMEN*			
PULL OR ALTER CASING CASING TEST AND C			SEMENT JOB C.
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
Spud well 11-30-91. Set 31 joints of 8 5/8" 24# casing at 1325' with 550 sacks of Class "C"			
cement. Circulated	to surface. Waited on c	ement 6 1/2 hou	rs. Tested casing to 800 psi.
Held OK.		•	nan
Ran 114 joints of 5	1/2" 15.5# casing and se	t at 5075' with	1150 sacks of Class "C" cement.
Waited on cement gr	eater than 24 hours. Tes	sted casing to 2	2000 psi. Circulated cement to
surface. Waited on	cement greater than 24 h	nours. Tested o	casing to 2000 psi. Held OK.
Total depth 5075'.			
I hereby certify that the information above	is true and complete to the best of my knowledge at	Land MgrPe	rmian Basin DATE 12-26-91
SIGNATURE Aschoel A	J. Newport	IIU!	тецелноме NO. 713 <u>589–84</u> 8
TYPE OR PRINT NAME	o. Henpo.		
(This space for State Use)	್ರಾಂತಿ		DATE
n. 156	Pige (1.14 Pige)		