

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Ilo Driscoll Rd., Artesia, NM 87410

WELL API NO.

30 025 31634

5. Indicate Type of Lease

STATE ☐

FED ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Lovington Paddock Unit

8. Well No.

134

9. Pool name or Wildcat

Lovington Paddock

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

GREENHILL PETROLEUM CORPORATION

3. Address of Operator

11490 WESTHEIMER, SUITE 200/HOUSTON, TEXAS 77077-6841

4. Well Location

Unit Letter M : 377 Feet From The South Line and 1111 Feet From The West Line

Section

31

Township

16S

Range

37E

NMIM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3811 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

PROFANILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud well 7-6-92. Ran 42 joints of 8 5/8" 24# casing and set at 1778' with 600 sacks of Class "C" cement. Circulate to surface. Waited on cement 9 1/2 hours; however, compressive strength meets minimum requirements. Tested casing to 900 psi. Held OK.

Ran 141 joints of 5 1/2" 15.5# casing and set at 6375' with 1000 sacks of Class "C" cement. Circulate to surface. Waited on cement greater than 24 hours. Tested casing to 2000 psi. Held OK. Total depth 6375'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Michael J. Newport

TITLE Land Manager/Permian Basin DATE 7-17-92

PRINTED NAME

Michael J. Newport

FILE NUMBER NO. 713/589-84

(This space for State Use)

Orig. Signed by
Paul Rantz
Geologist

APPROVED BY

TITLE

DATE

JUL 21 '92

COMMENTS ON APPROVAL, IF ANY: