

Geoscience Exploration CKO, Inc.
310 W. Wall, Suite 702-LB106
Midland, Texas 79701

Crescent -3- No. 1
Sec. 3 - Unit E, T-15-S, R-35-E
Lea County, New Mexico

Drill Stem Test Summaries

Page 1 of 1

DST No. 1

10,510' to 10,537' (27')
15"/60"/60"/180"
IHP 5207 FHP 5207
IF 90-90 FF 135-181
ISIP 271 FSIP 271
BHT 168

Recoveries: 120' DM
.05 ft.³ G @ 115#, 2250 cc W, Tr Oil

DST No. 2

10,922' to 10,975' (53')
15"/88"/65"/245"
IHP 5527 FHP 5527
IF 1085-1265 FF 1265-2389
ISIP 2842 FSIP 2434
BHT 165

Recoveries: 61 B0
3.8 ft.³ G @ 165#, 1600 cc Oil

DST No. 3

11,908' to 11,851' (57')
30"/60"/60"/180"
IHP 6078 FHP 6050
IF 263-317 FF 318-441
ISIP 4445 FSIP 4503
BHT 171

Recoveries: 1548' HGCM, tr 0.1
.73 ft.³ G @ 100#