

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-32922

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

8. Well No.

139

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter G : 2603 Feet From The North Line and 1358 Feet From The East Line

Section 18 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4215' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/22/02 MIRU Eunice Well Service. POH w/pump & rods. NU BOP. TAC would not release.

5/23/02 RU Rotary WL. Tbg. stuck @ 4570'. POH w/140 jts. 2-7/8" tbg. RIH w/bit & scraper on 2-7/8" tbg. Tag @ 4570'. POH w/2-7/8" tbg. bit & scraper. RU Signal WL & perforate Grayburg f/4180', 81', 4203', 08', 09', 33', 58', 59', 84', 98', 4317', 28', 33', 34', 52', 65', 68', 4399', 4400', 12', 22', 24', 34', 46', 85' & 4505' w/4 SPF. RD WL.

5/24/02 RIH w/pkr., SN & 2-7/8" tbg. Tag @ 4570'. POH. Set pkr. @ 4118'. RU Cudd Pump Service. Pressure test tbg. to 4000#. Csg. to 500#. Acidized Grayburg w/5000 gals. 15% NE-FE acid & 3000# rock salt. ATP 2850# @ 4.1 bpm. MTP 3300#. Best block 300#. Best break 500#. Flush w/30 bbls. fresh water. ISIP 2600#. 5 min. 2400#. 10 min. 2320#. 15 min. 2150#.

5/28/02 Unset pkr. POH w/2-7/8" tbg. LD AD-1 pkr. RIH w/2-7/8" tbg. Tbg. @ 4175'. SN @ 4140'. RD BOP. NU WH. RIH w/rods & 2-1/2" x 1-1/2" x 20' pump. Left well pumping to CMU Battery "A". RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II DATE June 13, 2002
TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE JUL 2 2002
ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER