8/7/97 806-27-68-20 Craig Japlino 17:C.S. 2/ac 31#1 ' Opened values 8/5/27 no rature racuum. at 8/6/97 sending letter & schematics

ankirming flendings

In the space below indica performed, listing wells	AM Time of Return	
Phillips Pet lo- 7 down Production	Aus Mui B" #1H-20	-17-33 - La
10 Wells Shatteric	Maljamar area Dexaco - Al	- Housekeeping
V - Underground Injection (related to injection p; resulting from injection injection and production trats. surface injection R - Inspections relation of the statement of the statement of t	Control - Any inspection of or roject. facility, or well or on into any well. (SNG. Indry on wells. water flows or pressure on equipment. plugging. etc.)	Hours UIC RFA Other BATURE OF SPECIFIC MELL OR PACILITY INSPECTED D = Drilling P = Production 1 = injection C = Compiled prod. inj. operations S = ShD U = Underwround Storage G = General Decration P = facility of idecation
	Time of Departure In the space below indice performed. listing wells Signature / uelel - Malyane / uele	Time of Departure 7 AM Time of Beturn In the space below indicate the purpose of the trip a performed, lighting walls or leages visited and any ac Signature Jack Strifting / utele - Malgamar Gree - P& Ac // utele - Malgamar Gree // utele - Malgamar

STATE OF NEW MEXICO



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION POST OFFICE BOX 1980 HOBBS. NEW MEXICO 88241-1980 (505) 393-6161

KCS Medalion 7130 South Lewis, Suite 700 Tulsa, Oklahoma 74136

Re: Vacuum 31 #1-0, Sec. 31, T16S, R35E

Gentlemen:

An Oil Conservation Division representatve recently witnessed a bradenhead test on the above referenced producing well.

The information available indicates a possible casing leak.

We request that you determine the cause of the strong vacuum both on the surface and intermediate casing, and make any repairs necessary to prevent damage to the affected formations. We request that you submit your proposal for correcting this problem on a sundry notice (C-103) no later than September 30, 1997.

We are enclosing copies of the test sheet for your information.

We request 24 hours notice prior to repairs in order to witness the operation.

Very truly yours

OIL CONSERVATION DIVISION

his Williams

Chris Williams Supervisor, District I

CW:bp

cc: William J. LeMay File

Enclosure

STATE OF NEW MEXICO



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

DIL CONSERVATION DIVISION POST OFFICE BOX 1980 HOBBS. NEW MEXICO 88241-1980 15051 393-6161

KCS Medalion 7130 South Lewis, Suite 700 Tulsa, Oklahoma 74136

Re: Vacuum 31 #1-0, Sec. 31, T16S, R35E

Gentlemen:

An Oil Conservation Division representatve recently witnessed a bradenhead test on the above referenced producing well.

The information available indicates a possible casing leak.

We request that you determine the cause of the strong vacuum both on the surface and intermediate casing, and make any repairs necessary to prevent damage to the affected formations. We request that you submit your proposal for correcting this problem on a sundry notice (C-103) no later than September 30, 1997.

We are enclosing copies of the test sheet for your information.

We request 24 hours notice prior to repairs in order to witness the operation.

Very truly yours

OIL CONSERVATION DIVISION

Chris Williams

Chris Williams Supervisor, District I

CW:bp

cc: William J. LeMay File

Enclosure

NEW MEXICO OIL CONSERVATION DIVISION CASING-BRADERHEAD TEST OPERATOR: INTERCOAST OIL & GAS and the second LEAGE: VACUUM "Si" POCL: NORTH VACUUM ATOKA-MORROW GAS 1641 L TR C FUCTAGE 660-S SECTION 31 TWN to S RANGE Trip and a TYPE LEASE F FOOTAGE 1980-E PRESS LHT . DATE 100, BEGAN GROER NO.. PASS/FAIL TEST DATE. TEST IVEE . OCD ACH: OPERATOR REP: SET AT TOP CHT CEMENTED - PRESSURE REMARKS CASING SIZE 495 Ø 5408x SURFACE 13 3/8 в 1.58953 4585 NDê INTERM-1 9 5/5 INTERM-2 . .. 12750 12.030 30031 PROD 5 1/2 THREAG . SEMARKS: COMPLETED 8/1/95 DATE REPAIR REPAIR LETTER DATE . TEST DATE27-Jun-96 TEST TYPE BHT PASS/FAIL 8P02 OCD REF: TURNACL FF OPERATOR REP: JIMMY SET AT TOP OMT CEMENTED PRESSURE REMARKS CASING SIZE 3" VAC-0 . 495 Ø 5406X SUBFACE 13 3/8 INTERM-1 9 5/8 4585 NDE ZIN VAC-1. ABOSX 100EBahaz 12750 12.0301 8805% 130 . eego 5 iza 125 GAS WELL TUB:NG 2 3/8 . SHC HO MEMARKS, THEN FOR J SHNO WORK AT THIS TIME. DATE REPAIR ACCAR ACTER GATE . TEAT OPTE 07-03-97 TEST TYPE PASS/FAIL Jach CCD REP: . REPARTOR REPA Chad BET AT TOP CHT CEMENTED PRZSURE REMARKS tereta erze 3 5488X Strong Vac no gange AGFACE 13 3/8 495 16:505 Strong Vac 4535 MDB 220 12758 1219384 800SX 100 gas well Sec. GATE REPAIRED