

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-33033

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

B-2148

7. Lease Name or Unit Agreement Name

Maljamar Grayburg Unit

1 Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P O. Box 2568 Hobbs, New Mexico 88421

8. Well No.

86

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter F : 2537 Feet From The North Line and 2603 Feet From The West Line

Section 4 Township 17S Range 32E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4218' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Plug back & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/07/02 MIRU Key Well Service. POH w/rods & tbg. RIH w/bit & scraper on 2-7/8" tbg. Tag @ 4332'. POH w/2-7/8" tbg., bit & scraper. RIH w/AD-1 pkr., SN & 2-7/8" tbg. Set pkr. @ 4146'. RU Hughes Service & pump 83 bbls. water @ 1600# down tbg. Did not communicate. Drop standing valve. Would not pressure up. RD Hughes. POH w/4 stands 2-7/8" tbg.

1/08/02 POH w/2-7/8" tbg., SN & AD-1 pkr. RU Hydrostatic Pipe Testers. RIH w/CIBP testing 2-7/8" tbg.. Set CIBP @ 4280'. POH w/2-7/8" tbg. RIH w/AD-1 pkr. & 2-7/8" tbg. to 4099'. Tested CIBP 2000#. Spot 110 gals. Scale converter across perfs. 3885'-4035'.

1/09/02 Swab back scale converter. POH w/2-7/8" tbg., SN & AD-1 pkr. RIH w/AD-1 pkr. & 2-7/8" tbg. to 1800'. Pkr. was sticking. POH w/2-7/8" tbg. AD-1 pkr. RIH w/nothed collar & 2-7/8" tbg. to 4200'. RU Cudd Services. Circulate hole w/100 bbls. fresh water. POH w/2-7/8" tbg. & nothed collar. RIH w/AD-1 pkr., SN & 2-7/8" tbg. Set pkr. @ 3835'. Cudd acidized Grayburg 3885'-4035' w/3000 gal.s. 15% NE-FE acid w/2200# rock salt. ATP 3280# @ 4.3 bpm. MTP 4120# @ 4.5 bpm. Best block 550#. Best break 200#. ISIP 2900#. 5 min. 2740#. 10 min. 2710#. 15 min. 2660#.

1/10/02 TP 1450#. POH w/2-7/8" tbg., SN & AD-1 pkr. RIH w/2-7/8" tbg. Tbg. @ 4266'. SN @ 4231'. ND BOP. RIH w/rods & 2-1/2" x 1-1/2" x 16' RHBC pump. Left well pumping to Battery.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mary Jo Turner

TYPE OR PRINT NAME

Mary Jo Turner

TITLE

Production Tech II

DATE

January 12, 2002

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY

TITLE

DATE

JAN 28 2002

CONDITIONS OF APPROVAL, IF ANY: