

YATES PETROLEUM CORPORATION
Robert AGX State #1
Section 20-T16S-R36E
Lea County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 11461-11617': TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 30". RECOVERY: 800' of fresh water cushion and 90' of drilling mud. SAMPLER: .04 cfg & 2300 cc mud. PRESSURES: IHP 5680; IFP 422-425; ISIP 580; 2nd FP 425-426; 2nd SIP 568; 3rd FP 427-427; FHP 5687

DST #2 11760-11890' (ATOKA): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 30". RECOVERY: 45' of drilling mud and 1169' of fresh water cushion. SAMPLER: 0 cfg, 2600 cc mud. PRESSURES: IHP 5876; IFP 610-613; ISIP 852; 2nd FP 603-617; 2nd SIP 751; 3rd FP 618-618; FHP 5877

DST #3 11905-12505' (ATOKA): TIMES: TO 20"; SI 60"; TO 60"; SI 60"; TO 30". RECOVERY: 1368' of cushion and 120' of rathole mud. SAMPLER: 2600 cc mud. PRESSURES: IHP 5910; IFP 669-672; ISIP 1061; 2nd FP 674-677; 2nd SIP 919; FFP 680-682; FHP 5912