WELL	NAME	AND NUMBE		"28" #1	Chit J			
LOCA:	rion_	Section	1480/3 1 28, T=15-S, R-3	S 0-2316 7-E, Lea Cou	nty, New Mexico	30-	025-336	284
operi	ATOR_	Rand Paul	son Oil Co., Inc	., 508 W. Wa	11, Suite 100, M	idland, T	exas 79701	``
DRILI	LING (CONTRACTOR	TMBR/Sharp Dril	ling, Inc.,	P.O. Drawer 10970), Midlan	d. Texas 7970	2
The undersigned herby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and that he has conducted deviation tests and obtained the following results:								
	Degre	ees @ Dept	h Degrees @	Depth	Degrees @ Depth	. 1	Degrees @ Dep	th_
	.50	° @ 400'		5,675'	1.00° @ 10,434	· -	· · · · · · · · · · · · · · · · · · ·	_
	.50	° @ 700'	1.75° @ 5	5,800'	1.00° @ 10,928	. <u>-</u>		
	1.00	° @ 1,191'	1.75° @ 5	3,923'	.50° @ 11,428°	. <u>-</u>		
	<u>.75</u> °	° @ 1,661'	1.25° @ 6	.046	1.75° @ 11,960'	· _		
-	.25	° @ 2,159'	1.50° @ 6	,295'	1.75° @ 12,350'	-		-
•	1.00°	° @ 2,657°	2.00° @ 6	,575'				
-	1.00°	° @ 3,063'	1.25° @ 6	,699'				_
-	.50°	e 3,561'	1.50 0 6	,930'				· -
-	-75°	@ 4,056'	75° @ 7	,170		_		_
-	1.50°	0 4,553'	1.00° (4 7	,662'		_		
. -	1.00°	@ 4,900'	1.00° @ 8	<u>,100'</u>				-
	2.00°	<u> </u>	1.00° @ 8	<u>,566'</u>		_		-
-	1.75°	@ 5,364'	75° @ 8	907'		, –	· · · · · · · · · · · · · · · · · · ·	-
_	1.75*	@ 5,488'	1.25° @ 9	,033'		_		-
_	1.50°	@ 5,582'	1.25° @ 9.	,530 °			····	_
Drilling Contractor TMBR/Sharp Drilling. Inc.								
s	ubscr	ribed and s	sworn to before m		By Phillips, Engineering Manager			
			KATHLEEN ROPER MY COMMISSION EXPIRES September 25, 1899		Kalkha	5 Ropu		
C	ommis	ion expire			Midlan		•	21