

Page 2 of 4-25-97 C-103
Bus Barn 4-1Y, Lea Co., NM
API No. 30-025-33776

03-12-97 continued

Load csg w/6 bbls 2% KCL w/2 GPT lo-surf 300, pump 4 bbls 2% KCL w/2 GPT lo-surf 300 2 BPM @ max PSI 2500#, unable to break down. SDFN

03-13-97 PU & TIH w/pkr, 3 jts 2-7/8" 8.7# N80 8RD tbg, pkr, 2-1/4" SN & 362 jts 2-7/8" L80 6.5# 8RD tbg to 11,545, RU & run GR/CCL, correlate to Neutron log dated 2/14/97. TOOH, PU 2-7/8" x 6" 6.5# N80 8 RD sub to space out RU Halliburton, circ. hole w/194 bbls 2% KCL w/2GPT lo-surf300 to flush out acid, set pkr @ 11,500' w/21,000# compression, ND BOP's, NU wellhead, load cst w/ 3 bbls 2% KCL w/2GPT lo-surf 300 test pkr to 1000#

03-14-97 Frac Strawn

total load in Strawn, 94 BLWTR, ISIP 8108#, 5 min 6740#, 10 min 6548#, 15 min 6377#, bleed off well, RD Halliburton & tree saver, ND well head, NU BOPs, TOOH w/358 jts 2-7/8" L80 6.5# 8RD tbg, Uni III pkr, 3 jts 2-7/8" L80 8.7# 8RD tbg & Uni V pkr

Well shut in & being re-evaluated

Barbara J. Bale