

YATES PETROLEUM CORPORATION
Brunson AQK State Com #1
Section 10-T16S-R35E
Lea County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 10510-10600' (Wolfcamp): TIMES: TO 15"; SI 60"; TO 60"; SI 180". RECOVERY: 60' of rathole mud. SAMPLER: 2600 cc mud. PRESSURES: IHP 4910; IFP 22-55; ISIP 325; FFP 54-69; FSIP 235; FHP 4921

DST #2 11670-11825' (Atoka): TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY: 655' of cushion and 202' of gas cut mud. SAMPLER: 2.08 cfg & 350 cc mud. PRESSURES: IHP 5919; IFP 397-404; ISIP 3081; FFP 275-396; FSIP 4497; FHP 5919

DST #3 11966-12010' (Atoka): TIMES: TO 20"; SI 60"; TO 65"; SI 180"; TO 60"; SI 33". RECOVERY: 1164' of cushion with trace of oil and 246' of mud. SAMPLER: 4.06 cfg, 300 cc oil and 600 cc mud. PRESSURES: IHP 6072; IFP 582-611; 2nd FP 544-572; 2nd SIP 4040; 3rd FP 463-611; 3rd SIP 3486; FHP 6058. NOTE: 3rd SI due to bleeding gas off drillpipe after 3rd flow