

YATES PETROLEUM CORPORATION
Field APK State Com #3
Section 2-T16S-R35E
Lea County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 11770-11890' (Atoka): TIMES: TO 30"; SI 60"; TO 60"; SI 120". RECOVERY:
742' of water cushion. SAMPLER: 2600 cc mud. PRESSURES: IHP 6023; IFP 358-369;
ISIP 680; FFP 376-378; FSIP 506; FHP 6062

DST #2 12070-12185' (Atoka): TIMES: TO 15"; SI 60"; TO 60"; SI 240". RECOVERY:
318' of water cushion, 186' of slightly gas cut mud and 1603' of water. SAMPLER:
.04 cfg and 2575 cc water. PRESSURES: IHP 6250; IFP 440-579; ISIP 350; FFP
693-998; FSIP 3547; FHP 6231

DST #3 12294-12358' (Morrow): TIMES: TO 15"; SI 60"; TO 60"; SI 240". RECOVERY:
582' of fresh water cushion and 1006' of gas cut mud with trace of oil. SAMPLER:
4.06 cfg, 300 cc oil and 50 cc mud. PRESSURES: IFP 447-495; ISIP 6400; 2nd FP 387-660;
FSIP 6352; FHP 6280