

State of New Mexico
Energy, Minerals and Natural Resources Department

DISTRICT I
P.O. Box 1980, Hobbs NM 88240
DISTRICT II
P.O. Drawer DD, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-34908

5. Indicate Type of Lease
State ☐ FEE ☒

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

BIG BEAR ATN

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

8. Well No.
1

2. Name of Operator
Yates Petroleum Corporation
3. Address of Operator
105 South 4th., Artesia, NM 88210

9. Pool Name or Wildcat
Townsend Perma Upper Perm

4. Well Location
Unit Letter SI: 1980 Feet From The South Line and 1120 Feet From The East Line
Section 29 Township T15S Rang R35E NMPM Lea COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4001' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER Re-entry ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-25-01- MIRT. Notified Debbie w/ the FAA of intent to MIRT. Notified Bill Gatchall, manager @ Zip Franklin Memorial airport @ 8:15 am 7-25-01.

7-27-01- Drilled cement to 40'. Picked up drill pipe & drill collars. Drilled cement. PU drill pipe. Start drilling cement @ 2:00 pm 7-27-01.

7-28-01- Washing to bottom. Circ clean hole. Tagged cement @ 4540'. Drilled cement to 7930'-6230'.

7-30-01- Drilled cement from 9740-9860'.

7-31-01- circ & condition, heaving shale.

8-1-01- Wash & ream thru shale.

8-2-01- Wash & ream. Trip- remove jets. SLM.

8-11-01- Wash & ream. Circ @ 12,103'. TD 8-1/4" hole @ 4:30 am 8-11-01.

8-13-01- Lay down drill pipe.

8-14-01- ND & jet pits. LD DP & DC. Rigged up & run 287 jts (12,165') casing, set as follows:

23 jts 5-1/2" 20# P110 SB (957.95')

14 jts 5-1/2" 17# HCP110 SB (554.28')

25 jts 5-1/2" 17# P110 varn (1070.97')

I hereby certify that the information above is a true and complete to the best of my knowledge and belief.

continued on next page

SIGNATURE Donna Clack

TITLE Operations Technician

DATE 11/12/01

TYPE OR PRINT NAME Donna Clack

TELEPHONE NO 505-748-1471

(This space for State Use)

APPROVED BY

TITLE

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE

FEB 26 2002


CONDITIONS OF APPROVAL, IF ANY:

YATES PETROLEUM CORPORATION
BIG BEAR 'ATN' #1
Section 29-15S-35E
Lea County, New Mexico

222 jts 5-1/2" 17# L-80 varn (9453.17')

3 jts 5-1/2" 20# P110 varn (129.53')

Float shoe srt @ 12,103'. Float collar set @ 12,103. Bpttom marker @ 11,167', top marker @ 10,613'. Cemented w/ 1025 sx PVL + 1#/sx D44 + 4# /sx D24 + 0.2% D65 + 0.3% D167 + 0.2% D46 + 0.7% D800 + 0.05% gal/sx D801 (yld 1.36, wt 13.5). PD @ 11:45 pm 8-13-01. Bumped plug to 2000 psi for 2 min, float & casing held OK. 8-14-01- iting on completion unit. Rig down. Set slips & cut off. Rig released @ 8:00 am 8-14-01.


Donna Clack
Operations Technician
January 25, 2002