



(SUBMIT ~~HOBBES OFFICE~~ O. C. C.)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office, ~~San Antonio~~
Lease No. **LC 065128F**
Unit **APPROVED**

OCT 28 1963

SUNDRY NOTICES AND REPORTS ON WELLS
G. HUBBLE
ACTING DISTRICT ENGINEER

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Yates Federal A-I **March 23**, 19 **23**
Well No. **1** is located **650** ft. from **N** line and **1980** ft. from **E** line of sec. **24**
N3/4NW/4 **24** **13S** **32E** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **Lea** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 2 inch tubing to 4767 circulated mud, spotted 100 feet cement plug 4667-4767. Spotted 20 feet plug at surface and placed regulation dry hole marker at location. Plugged and abandoned 3/23/63

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Yates Petroleum Corporation**

Address **309 Carper Building**

Artesia, N.M.

By *Richard C. Newman*

Title **Agent**