

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 069497

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☐ GAS ☐
WELL WELL OTHER **WIW**

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. BOX 1305, ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

330' FNL & 1650' FWL Sec.29;T-18S-R-32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

YOUNG UNIT

8. FARM OR LEASE NAME

9. WELL NO.

30

10. FIELD AND POOL, OR WILDCAT

YOUNG QUEEN

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec.29-18S-32E NMPM

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐**Convert to WIW**(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

This well was converted to injection as follows:

12-1-69 Cleaned out to 4030'

12-2-69 Perforated 2 jet shots per foot 3711'-30', 3735'-42', 3747'-49'

12-20-69 Fraced well with 500 gallons 15% regular acid, 36,000# of 20/40 sand
and 960 bbls fresh water

12-21-69 Cleaned out to 4030'

12-23-69 Put well on injection

Injection first five days averaged Upper Queen 152 bbls @ 250 psi,
Penrose 246 bbls @ 0 psi.

18. I hereby certify that the foregoing is true and correct

SIGNED

Samuel L. Butler

TITLE

Division Superintendent

DATE

1-27-70

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

JAN 29 1970

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side