

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 059592

Unit D.V. Lynch

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 12, 1946

Well No. 4 is located 660 ft. from [M] line and 660 ft. from [E] line of sec. 20

33/4 Sec. 20
(1/4 Sec. and Sec. No.)

19S
(Twp.)

32E
(Range)

S.M.P.
(Meridian)

East Lusk
(Field)

Lee
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3580 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well temporarily abandoned in accordance with Notice of November 9, 1943. Well has now been finally plugged and abandoned. Mudded hole to surface and set 10 sack cement plug on bridge in 2 5/8" casing at 850'. Also set 10 sack cement plug and set at surface and erected 4" by 10' steel marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company CULBERTSON & IRWIN, INC.

Address Box 1071
Midland, Texas

By [Signature]

Title President