


SCOUT REPC. *5th*

*South Maljamar*

NEW MEXICO OIL CONSERVATION COMMISSION



Company *Culbertson & Irwin (04100)*

*Govt.*  
Farm Name *Lynch* Well No. *1*

Sec. *21* Twp. *19* Range *32* County *Lea*

Feet from Line: N. *660* S. E. *660* W.

Elevation *9580* Method

Contractor

Spudded Completed *10-14-46*

**AMOUNT  
CASING & CEMENTING RECORD**

Size	Feet	Inches	Sax Cement

ACID RECORD Gals.	TA	TG
		TX
	TCA	TGI
	BX	TYo
	TY	TABo
	TSR	TPenn
Top Pay	TQ	TOrd

**TUBING RECORD**

No. of Quarts	From	To
S/	S/	S/
S/	S/	S/
S/	S/	S/

**SHOOTING RECORD**

No. of Quarts	From	To
S/	S/	S/
S/	S/	S/
S/	S/	S/

PACKER

Date		Date	
<i>8-20</i>	<i>Old ID 2816</i>		
<i>8-27</i>	<i>φ 30 90L</i>	<i>10-15</i>	<i>ID 3817L Plugged and Abandoned</i>
<i>9-3</i>	<i>φ 32 22L</i>		
<i>9-10</i>	<i>φ 36 63L</i>		
<i>9-17</i>	<i>φ 37 91L</i>		
<i>9-24</i>	<i>ID <del>3824</del> 3817L; PB 2955; Intg for water shut off</i>		
<i>10-1</i>	<i>SDO - Top plug</i>		
<i>10-8</i>	<i>ID 3817L PB 2896</i>		