



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.  
Approval expires 12-31-60.

Land Office Santa Fe  
Lease No. NM 016791  
Unit L

RECEIVED  
SEP 21 1960  
ARTESIA OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Plugging	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 12, 1959

Well No. 1 is located 1650 ft. from N line and 990 ft. from E line of sec. 21  
Atlantic  
NW/4 SW/4 Section 21 19S 32E NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
G East Lusk Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to T.D. of 2710'. No oil and Sulphur water from 2700-2710'. Hole filled up 180' with water. Ran 10 sack cement plug on bottom of hole. Mudded hole back to bottom of surface casing at 917'. Ran 10 sack cement plug in bottom of surface casing. Mudded hole back to surface and set marker in cement and cleaned up location.

878 28# Surf 159 @ 917, "cut" pld all 159

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kersey & Company

Address Box 305  
Artesia, New Mexico

By Harold Kersey

Title Owner