

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Carper Drilling Company, Inc.				Address Artesia, New Mexico			
Lease State "AA"		Well No. 1	Unit Letter G	Section 32	Township 17 S	Range 33 E	
Date Work Performed 1-5-62		Pool Maljamar			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- Beginning Drilling Operations
 Casing Test and Cement Job
 Other (Explain):
 Plugging
 Remedial Work
 Perforating & fracturing

Detailed account of work done, nature and quantity of materials used, and results obtained.

T. D. 4810'
P.B.T.D. 4522'
Perforated 4345'-65', 4370'-73'; 4390'-95'; 4408'-12'; 4421'-25'; 4442'-57'; 4466'-69'; and 4488'-92' w/2 jets per foot
Acidized with 500 gallons NE 15% acid.
Fractured with 16,800 gallons lease crude w/800# Adomite and 25,200 lbs. sand using 90 balls.
After recovery of all load, well flowed 100 BOPD on 3/4" choke.

Witnessed by C. E. Storm	Position Prod. Supt.	Company Carper Drilling Company, Inc.
------------------------------------	--------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA


D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter		Tubing Depth	Oil String Diameter	Oil String Depth
Perforated Interval(s)				
Open Hole Interval			Producing Formation(s)	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name J. Marshall Lowry
Title	Position Vice-President
Date	Company Carper Drilling Company, Inc.