FORM C-103 (Rev 3-55)

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106) Name of Company Address Carper Drilling Company, Inc. Artesia, New Mexico Well No. Range Unit Letter Section Township Carper-Cockburn-State, "B" 188 33E Pool Date Work Performed County 10-4-61 Undesignated THIS IS A REPORT OF: (Check appropriate block) Casing Test and Cement Job Beginning Drilling Operations T Other (Explain): Remedial Work Plugging Perforating, Fracing & Completion
Detailed account of work done, nature and quantity of materials used, and results obtained. T.D. 4073'. P.B.T.D. 4040'. Perforated 4005'-4927' with 2 jets per foot. Spotted 250 gallons 15% NE acid. Fraced with 11,000 gallons lease crude plus 16,500# sand. Pressure increased above 5000 psi and casing burst. Found hole in casing at 177', backed casing off at 217' and replaced burst casing joint. Total load 360 barrels. After recovery of load oil, well flowed 100 barrels in 24 hours. Witnessed by Position Company Prod. Supt. Carper Drilling Company, Inc. 2. Storm FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA DF Elev. T D PBTD Producing Interval Completion Date Tubing Diameter Tubing Depth Oil String Diameter Oil String Depth Perforated Interval(s) Open Hole Interval Producing Formation(s) RESULTS OF WORKOVER Oil Production Gas Production Water Production Date of GOR Gas Well Potential Test Test BPD MCFPD BPDCubic feet/Bbl MCFPD Before Workover After Workover I hereby certify that the information given above is true and complete to the best of my knowledge. OIL CONSERVATION COMMISSION Approved by Title Position Vice President Date