

NUMBER OF COPIES RECEIVED
DISTRIBUTION

SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
TRANSPORTER	OIL	
	GAS	
PRORATION OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company James P. Dunigan				Address 415 Citizens National Bank Building Abilene, Texas			
Lease State "B"	Well No. 3	Unit Letter D	Section 2	Township 18 S	Range 33 E		
Date Work Performed 7-12-62	Pool Corbin Abo			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☒ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spudded well on 7-12-62. On 7-12-62 ran 320' of new 11 3/4" O.D. Spiral Weld 23.80# casing. Cemented with 300 sacks of regular cement with 2% Calcium Chloride. Let cement set for 24 hours. Drilled out cement to bottom of casing shoe and pressured casing up to 600 PSL. Pressure held for 30 minutes without decreasing.

Cement completed

Witnessed by Bubba Spears	Position Agent	Company James P. Dunigan
-------------------------------------	--------------------------	------------------------------------



FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

Oil CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by 		Name 	
Title		Position Superintendent	
Date		Company James P. Dunigan	