

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office .....

Lease No. ....

Unit .....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL .....	SUBSEQUENT REPORT OF WATER SHUT-OFF .....
NOTICE OF INTENTION TO CHANGE PLANS .....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING .....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF .....	SUBSEQUENT REPORT OF ALTERING CASING .....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL .....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR .....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE .....	SUBSEQUENT REPORT OF ABANDONMENT .....
NOTICE OF INTENTION TO PULL OR ALTER CASING .....	SUPPLEMENTARY WELL HISTORY .....
NOTICE OF INTENTION TO ABANDON WELL .....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 16, 1946

Well No. 2 is located 1980 ft. from N line and 680 ft. from W line of sec. 9  
SE-9 (NE 1/4 SE 1/4) 183 32E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Corbin Lea County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3990 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run tubing to bottom of 5 1/2". Mixed and pumped in 200 sacks of cement. Mudded well to 825 feet. Mixed and pumped in 500 sacks of cement. Mixed and pumped in cement solid from 825 feet to surface.

Regulation marker set up.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company LEA COUNTY CASING PULLERS

Address 814 West Harland

Hobbs, New Mexico

By W. R. Hines

Title Office Manager.