

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Company THE BRITISH AMERICAN OIL PRODUCING COMPANY Box 2513, Midland, Texas
(Address)

Lease NEW MEXICO Well No. 1 Unit T S 12 T 13 S R 33E

Date work performed June 14, 1955 POOL Undersaturated.

This is a Report of (Check appropriate block) ☒ Result of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Dry tested casing. Bailed hole dry at 9:05 AM. Let hole stand three hours. Ran bailer and found no fluid entry.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl. Date _____

Tbng Dia. _____ Tbng. Depth _____ Oil String Dia _____ Oil String Depth _____

Perf. Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

Oil Conservation Commission

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name _____

Name _____

Title _____

Position _____

District Superintendent

Date _____

Company _____

The British American Oil Producing Co.