State of New Mexico Energy, herals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

, NM 88240 3

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL	CONS	ERVA"	TION	DIVISI	ON

310 Old Santa Fe Trail, Room 206	
Santa Fe, New Mexi∞ 87503	

WELL API NO. 30-025-01644						
5. Indicate Type of Federal	Lease STATE	FEE 🗌				
6. State Oil & Gas	Lease No.					

SUNDRY NOTICES AND REPORTS ON WEL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PEI (FORM C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name			
1. Type of Well: OIL OAS WELL OTHER WIW	EK Queen Unit			
2. Name of Operator Seely Oil Company	8. Well No. 611			
3. Address of Operator 815 W. 10th St., Fort Worth, Tx. 76102	9. Pool name or Wildcat EK-Yates-SR-Queen			
4. Well Location Unit Letter I : 2310 Feet From The South	Line and 660 Feet From The East Line			
Section 24 Township 18S Ra	ange 33E NMPM Lea County			
//////////////////////////////////////	8 RKB			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK X ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB			
OTHER:	OTHER:			
and the second description of the second described	and aire nortinest dates, including estimated date of starting any proposed			

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The cement lined tbg. and pkr. were removed from the subject well. The csg. was cleaned out to PBTD of 4432' RKB. A plastic lined AD-I pkr. & 136 jts. 2-3/8" Salta lined tbg. were installed. Pkr. set @ 4252' RKB. The csg. was tested to \$200 psi for 30 minutes. An NMOCD representative witnessed the test (chart enclosed).

Seely Oil Company respectfully requests permission to resume water injection into the Queen interval on this well.

Thereby certify that the information above is true and complete to the best of my SIGNATURE Wand P. Donderson	nowledge and belief. TITLE Petroleum Engineer DATE 4/17/00	
TYPEOR PRINT NAME David L. Henderson	TELEPHONE NO. 817/332-1377	
(This space for State Use)		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TIME DATE DATE	

