		NEW	MEXICO OI	L CONSE	ERVAT	וסא כ	OIZZIMMO:	10888 OFFIC	FORM C-103 (Rev 3-55)	
		MIS	SCELLANE	OUS RI	EPOR1	7S ON	WELLS ISSO	MARIO	e ucc	
		(Submit to	appropriate Di	strict Offi					3:14	
						Address 309 Carper Bldg., Artesia, M. M.				
Lease O	nio Angle	St. B	Well No.		Letter F	Section 2	Township 17	Ran	ge 34	
Date Work Performed Pool Vacuum					County					
			THIS IS A REP	ORT OF: ((Check a	propria	te block)			
Beginni Pluggin	ng Drilling Oper	Casing Test and Cement Job Other (Explain): Remedial Work								
_	/40 frac	sand. Al	l oil wa	s reco	ver e ć	i and	lwell m	ade 50 blbl.	s, per	
Witnessect 1/1 fton Loyd Position Prod. St										
				DRIGINAL		ATA	1=			
D F Elev. T D 4728			P			Producing 12'		6-22-57		
Tubing Diameter 1 Tubing			\$50'	Oil String D 5-1/2			Oil String Depth		pth	
Perforated In	iterval(s)									
Open Hole Interval 4672 to 4684						Producing Formation(s)				
			RE	SULTS O	FWORK	OVER				
Test	Date of Test		oduction PD	Gas Produc MCFP			Production 3 P D	GOR Cubic feet/Bbl	Gas Well Potential MCFPD	
Before Workover	1-15-60	11		13.5			Mone	1525		
After Workover	2-5-60	40		53.4			Mone	73 5		
_	OIL CONS	ERVATION COA	MISSION	191			fy that the in my knowleds		ove is true and comple	
Approved by						Name to life hope				
Title					Positio		oduction	Superinte	ndent	
Date						ny S.	P. Yate	8		