
Submit 2 papies	State of	New Mexico		_	
Submit 3 copies to Appropriate District Office	E yy, Minerals and Nat	tural Resources Department			orm C-103 evised 1-1-8
EISTRICT I	OIL CONSERVA	ATION DIVISION	WELL API NO.		
P.O. Box 1980, Hobbs, NM 88240	P.O. Bo	-	WEEE/WING.	3002502292	
DISTRICT II	Santa Eo Now N	Mexico 87504-2088	5. Indicate Type		
P.O. Box Drawer DD, Artesia, NM 88210	) Canta i e, New i	WEXICO 07 304-2000	indicate type	STATE 🗸	FEE [
DISTRICT III			6. State Oil / Gas	Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410				858150	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  (FORM C-101) FOR SUCH PROPOSALS.			7. Lease Name or Unit Agreement Name WEST VACUUM UNIT		
1. Type of Well: OIL GAS WELL WEL					
Name of Operator     TEXACO EXPLORATION & PRODUCTION INC.			8. Well No.	38	
3. Address of Operator 205 E. Bender, HOBBS, NM 88240			9. Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES		
4. Well Location			11.1000.	. C. T. I DOI TO CANT AND	DICES
Unit Letter A :	330 Feet From The	NORTH Line and 660	_Feet From The	EAST Line	;
Section 5	Township 18S				
Occurr 5	l ownship 100	Range <u>34E</u> Ni	/IPM	LEA COU	NTY
A Company of the Comp	10. Elevation (Show whether D		APM	LEA COU	NTY
Farmer Grand Completed Company	10. Elevation (Show whether D				NTY
Farmer Grand Completed Company	10. Elevation (Show whether D	F, RKB, RT,GR, etc.) The Nature of Notice, Report	, or Other Dat		
11. Check A	10. Elevation (Show whether D	F, RKB, RT,GR, etc.) The Nature of Notice, Report	, or Other Dat	a	
11. Check A NOTICE OF INTENTIC	10. Elevation (Show whether D ppropriate Box to Indicat DN TO:	F, RKB, RT,GR, etc.) The Nature of Notice, Report	, or Other Dat JBSEQUEN <sup>™</sup>	a F REPORT OF	
11. Check A  NOTICE OF INTENTIC  PERFORM REMEDIAL WORK	10. Elevation (Show whether D ppropriate Box to Indicat DN TO: PLUG AND ABANDON	F, RKB, RT,GR, etc.)  The Nature of Notice, Report  State Remedial Work  COMMENCE DRILLING OP	, or Other Dat JBSEQUEN <sup>™</sup> ✓ A ERATION ☐ F	a  T REPORT OF  LITERING CASING	
11. Check A  NOTICE OF INTENTIC  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	10. Elevation (Show whether D ppropriate Box to Indicat DN TO: PLUG AND ABANDON	F, RKB, RT,GR, etc.)  The Nature of Notice, Report  State	, or Other Dat JBSEQUEN <sup>™</sup> ✓ A ERATION ☐ F	a T REPORT OF LITERING CASING LUG AND ABANDONN	
11. Check A  NOTICE OF INTENTIC  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	ppropriate Box to Indicate DN TO: PLUG AND ABANDON CHANGE PLANS  erations (Clearly state all perticular state all perticular state) EW/PKR FLUID. TEST CSG T	F, RKB, RT,GR, etc.)  Te Nature of Notice, Report SU REMEDIAL WORK COMMENCE DRILLING OP CASING TEST AND CEME! OTHER:  nent details, and give pertinent d	, or Other Dat  JBSEQUEN  A ERATION  F  NT JOB  REQUEST T  ates, including es	T REPORT OF ALTERING CASING ALUG AND ABANDONM A STATUS	ENT

Mais Approval of Temporary Abandonment Expires **Engineering Assistant** SIGNATURE\_ TITLE DATE \_\_\_\_5/2/00 TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405 (This space for State Use) APPROVED 86 NDITIONS OF APPROVAL IF ANY:

DeSoto/Nichols 12-93 ver 1.0



From: Siamak Safargar To: Tim Miller

Subject: Abandoned Salvage Deferred for WVU Wells

In our recent review of the producers on West vacuum Unit, we identified two wells (WVU #21 & WVU #38) for temporary abandonment. WVU #21 was a temporary abandoned well that was brought back on production after our recent work on converting four wells to injectors. WVU #21 producers 1 oil/ 23 water on the average. We have learned of a possible casing problem on this producer as well. Our other candidate for ASD is WVU #38. This producer is currently inactive because of a failure. We have been experiencing a failure every other year on this well. This well is located on the southwestern part of the field and does not contribute much to the production on WVU (4 oil/ 110 water on average). Buckeye team does not see any immediate and near future potential for this well also. Therefore, to take the appropriate credit, Buckeye team requests Abandoned Salvage Deferred (ASD) status for these two wells.

West Vacuum Unit #21 West Vacuum Unit #38

Siamak Safargai

Prod. Engl., Buckeye FMT March 8, 2000

Approved By: A DAM

Date: 3-10-00

Both wells are classified ASD 4/26/00 P.W. Muiely