

HUMBLE OIL & REFINING COMPANY

Hobbs, New Mexico

November 29, 1942 11 AM 10 45

Tabulation of all deviation tests run on New Mexico State "BO" Well
#5, Unit G, Section 12, T-18-S, R-34-E, Lea County, New Mexico

<u>DEPTH</u>	<u>DEGREES OF DIVIATION</u>
150	1/4
300	3/4
565	1/4
815	1/2
1065	1/2
1300	3/4
1450	1/2
1600	3/4
1750	3/4
1810	3/4
1970	3/4
2150	3/4
2335	3/4
2440	3/4
2500	3/4 +
2560	1-1/4
2710	1
2775	1-1/4
2840	1-1/4
2900	1-1/2
2940	1-1/2
3000	1-1/4
3060	1-1/4
3185	1-1/4
3245	1-1/4
3315	1-1/4
3435	1-1/4
3700	1-1/2
3820	1-1/2
3940	1-3/4
4075	1/3/4
4170	2
4260	2-1/4
4360	2
4450	2-1/4
4550	2-1/2
4635	2-1/2
4735	2-3/4
4800	2-1/2
4890	2-3/4
5170	2-1/2
5270	2-1/2
5365	2-1/2
5450	2-1/4