

Submit 3 Copies
to Appropriate
District Office

Energy, Minerals and Natural Resources Department

Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-02328

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
LG-3406

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Central EK Queen Unit

1. Type of Well:
OIL WELL GAS WELL OTHER Water Injection

8. Well No.
001

2. Name of Operator
Seely Oil Company

9. Pool name or Wildcat
EK Yates-SR-Queen

3. Address of Operator
815 W. 10th St., Fort Worth, Tx. 76102

4. Well Location
Unit Letter D : 660 Feet From The North Line and 661.5 Feet From The West Line

Section 17 Township 19S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4080' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Convert to Water Injection</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/31/00

140 jts. of 2-3/8" Salta lined tbg. has been run with a plastic lined AD-I pkr. Pkr. set @ 4391' RKB. Annulus was loaded with pkr. fluid & tested to 400 psi (chart enclosed).

Seely Oil Company respectfully requests permission to begin injection.

Inj. 6-1-00. SI 7/00 to retest. Back on inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David L. Henderson TITLE Petroleum Engineer DATE 5/31/00

TYPE OR PRINT NAME David L. Henderson TELEPHONE NO. 817/332-1377

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY
CARY WINK
FIELD REP. II

JUN 05 2000