


SCOUT REPORT NEW MEXICO

OIL CONSERVATION COMMISSION



Company PHILLIPS
 Farm Name El Rio Well No. 2
 Land Classification 100%
 Sec. 1 Twp. 12S Range 35E County Doña Ana
 Feet from Line: 0 N. 0 S. 0 E. 660 W. 0
 Elevation _____ Method Rotary
 Contractor O. Wells Scout _____
 Spudded 6-26 Completed 7-10 Initial Production _____
 Bond Status Blanket

Casing and Cementing Record

Size	Feet	Inches	Sax Cement
<u>100</u>	<u>813</u>		<u>741</u>
<u>2</u>	<u>4637</u>		<u>20' Port</u>

Gals.

1000
 Prod. _____ Date _____
 Prod. _____ Date _____
 Top Pay 4327 Total Depth _____

SHOOTING RECORD

No. of Quarts _____ Shot at _____ Feet _____
 No. of Quarts _____ Shot at _____ Feet _____

Date		Date	
<u>6-22</u>	<u>C & P 2 Drilling</u>		<u>Flow 12 1/2 Bbls/hr</u>
<u>6-29</u>	<u>T.D. 5000 SD 1 in water</u>		<u>" 22 1/2 Bbls/hr</u>
<u>7-5</u>	<u>Q 1860 X 2 A</u>		<u>After Acid</u>
<u>JUL 12 1938</u>	<u>Q 3111 A F Q 4 P</u>		<u>1 P. 196 Bbls/hr</u>
<u>JUL 15 1938</u>	<u>Q 3111 A F Q 4 P</u>		<u>1" Choke</u>
<u>JUL 25 1938</u>	<u>Q 3111 A F Q 4 P</u>		
<u>AUG 2 - 1938</u>	<u>Q 3111 A F Q 4 P</u>		
<u>AUG 9 - 1938</u>	<u>Q 3111 A F Q 4 P</u>		
<u>AUG 16 1938</u>	<u>N.R.</u>		
	<u>T.D. 4037 L</u>		
	<u>Cased 4601-17</u>		
	<u>Rec 100% permeability</u>		
	<u>Cased 4601-27</u>		
	<u>100% permeability</u>		

12

[The page contains faint, illegible markings and bleed-through from the reverse side.]