



APPROVED

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPT.

INTERIOR

GEOLOGICAL SURVEY

Budget Bureau No. 49-2288.4
Approval expires 12-31-60.

Land Office Roswell, N.M.

Lease No. L.C.-032233-B

Unit P

Federal Bowers, B.

RECEIVED

AUG 11 1960

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 9

1960

Well No. 3-A is located 330 ft. from {N} line and 700 ft. from {E} line of sec. 20
SE/4 Section 20 18-S 38-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Hobbs Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A 25 sx plug was run to total depth. 589' of casing was recovered and the tubing was run back to this point and a 25 sx plug was spotted. The tubing was pulled up and a 50' plug was spotted below the 10-3/4" and 50' inside the 10-3/4" casing. A 10 sx cement plug was spotted in the top and a marker set.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C. H. Sweet Oil Company

Address Box 1115
Hobbs, New Mexico

By

Title

Operator