



Form 9-331a  
(Feb. 1951)



Land Office Las Cruces  
Lease No. 032233 (B)  
Unit \_\_\_\_\_  
Humble No. 163110  
Federal Bonus B

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, N. M. October 19, 1953

Well No. 4 is located 1980 ft. from S line and 1980 ft. from E line of sec. 25

NW 1/4 of SE 1/4 T-18S R-38E  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
East Hobbs (San Andres) Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Attempted to treat with 500 gallons mud acid. Wilson packer would not reset.  
Pulled same out and reran tubing and Guiberson packer.

Treated perforations from 3995 to 4030' with 500 gallons mud acid. Swabbed well dry.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Co.

Address Box 2347, Hobbs, N. M.

By M. M. V. Lugen

Title District Superintendent

mob/mcb