

NEW MEXICO STATE LAND OFFICE
OFFICE OF THE STATE GEOLOGIST
SANTA FE, NEW MEXICO

MISCELLANEOUS REPORTS ON WELLS

Submit this report in duplicate to the State Geologist or proper Oil and Gas Inspector within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of water shut-off, result of abandonment of well, and other important operations, even though the work was witnessed by the State Geologist or Oil and Gas Inspector. Reports on minor operations need not be signed and sworn to before a notary public, but such operations should be witnessed by an Oil and Gas Inspector if possible.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF SHOOTING WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF WATER SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF ABANDONMENT OF WELL		REPORT ON ACIDIZING WELL	X

Mr. **F. J. Vesely** State Geologist, **Wink, Texas.** **August 8th, 1935.**
Santa Fe, N. Mex. PLACE DATE

Following is a report on the work done and the results obtained under the heading noted above at the **REPOLLO OIL COMPANY** **W. D. GRIMES** Well No. **2 (2)** in the **NW/4** of Sec. **20**, T. **18S**, R. **36E**, N. M. P. M., **HOBBS** Oil Field, **LEA** County.

The dates of this work were as follows: **July 23rd & 24th, 1935.**

Notice of intention to do the work was (was not) submitted on Form SG _____ on _____, 19____, and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Well treated July 23, 1935 with 3000 gallons acid and 40 bbls. oil load, by Dowell & Son Incorporated, Midland, Michigan.

Well treated again July 24th, 1935 with 8000 gallons acid and 110 bbl. load of oil by Dowell Inc., Midland, Midland.

Casing:- 6-5/8" set at 3874' with 250 sacks cement

Formation treated:- Line 4167-4243 Total depth 4243'

Well flowed 400 bbls. oil in 2 hrs flowing wide open thru casing after 3000 gal. acid treatment.

Well flowed 340 bbls. in 1 hr. & 40 minutes wide open thru casing after 8000 gal. acid treatment.

Well now being produced at allowable.

Subscribed and sworn to before me this

_____ day of _____, 19____.

NOTARY PUBLIC.

My commission expires _____

I hereby swear or affirm that the information given above is true and correct.

Name **L. Durrett**

Position **Dist. Superintendent.**

Representing **Repollo Oil Company**

Address **Wink, Texas- Drawer P**

Remarks: **O.K. F. Vesely**
09. 1935

NAME

TITLE

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED

[illegible]

On the 1st of March 1944, the work was resumed at Town 20 and continued until the 15th of March 1944. The work was then discontinued for the purpose of the survey.

THESE TWO BROTHERS WERE BORN ABOUT 1870-1875 IN THE
 IN THE DISTRICT OF COLUMBIA, D.C. THE BROTHERS WERE
 BORN IN THE DISTRICT OF COLUMBIA, D.C. THE BROTHERS WERE
 BORN IN THE DISTRICT OF COLUMBIA, D.C. THE BROTHERS WERE

1. The first of these is the fact that the Commission has not yet received any information from the Government of the United Kingdom regarding the proposed changes to the law of the United Kingdom regarding the treatment of the British Commonwealth countries.

1. The first step in the process of the investigation is the identification of the problem. This is done by the investigator who is responsible for the study. The investigator must first identify the problem that he or she is investigating. This is done by the investigator who is responsible for the study. The investigator must first identify the problem that he or she is investigating.

[illegible]

• addition of new genes to genome over time

Address _____
City _____ State _____ Zip _____
Telephone _____
Company Name _____
Department _____
Job Title _____

[illegible]