MISCELLANEOUS REPORTS ON WELLS SEP 30 1953 ICATE to the District Office, Oil Conservation Commission Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

## Indicate Nature of Report by Checking Below

REPORT ON BEGINNING	REPORT ON RESULT OF TEST	REPORT ON	
Drilling operations	OF CASING SHUT-OFF	REPAIRING WELL	
REPORT ON RESULT	REPORT ON RECOMPLETION	REPORT ON Tests	X
OF PLUGGING WELL	OPERATION	(Other) for Casing Leek	

September 29, 1953 Honument, New Maxioo

Following is a report on the work done and the results obtained under the heading noted above at the

Amerada Petroleum Corporation (Company or Operator)	STATE "B" (Lease)		
Ken Wood Hidland, Texas (Contractor)	Well No		
T 18, R. 38, NMPM.,	Pool,		
The Dates of this work were as folows:			

Cross out incor

and approval of the proposed plan (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

## 1. Ran B.H.P. survey and temperature survey after 24 hours shut-in.

- 2. Attempted to bled down surface connections. Had oil flow from 9 5/8" casing.
- 3. Ran two additional temperature surveys while flowing 9 5/8" casing.

Could not find location of leak in 7" casing. Moving rig over well

to perform workover.

Witnessed by

Petroleum Engineer Amerada Petroleum Corporation (Title)

Approved: OIL CONSERVATION COMMISSION NU Engineer District (Dite) (Title)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name D.C.Cappo

Position......District.Superintendent Representing. Amereda Petroleum Corporation