(Title)

I hereby certify that the information given above is true and complete

Name C. C. Wilson

Position Dist. Supt.

Representing Continental Gil Co.

Address Box 127 - Hopbs. N.M.

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 they latter the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off leading of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING REPORT ON RESULT OF TEST REPORT ON DRILLING OPERATIONS OF CASING SHUT-OFF REPAIRING WELL REPORT ON Temperature and REPORT ON RESULT REPORT ON RECOMPLETION OF PLUGGING WELL **OPERATION** Pressure survey and X bradenhead check Hobbs, N.M. Following is a report on the work done and the results obtained under the heading noted above at the Continental O11 Co. (Company or Operator) (Contractor) , Well No. 2 in the 45 1/4 SW 1/4 of Sec. 29 , 18 R 38 NMPM, Hobbs Pool, Lea County Notice of intention to do the work (was) (was not) submitted on Form C-102 on.....(Cross out incorrect words) and approval of the proposed plan (was) (was not) obtained. DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED With tubing pressure 700 pai, 7" casing pressure 1000 pai, 9 5/8" bradenhead Check: casing pressure 300 psi, and 12 3/4" casing pressure 0 psi, the 9 5/8" bradenhead was opened. The 9 5/8" casing pressure dropped to 0 psi in 15 minutes, and the 7" casing pressure remained at 1000 psi. Temperature and Praesure Survey: On 6-16-40 due to presence of holes in the 3" tuking and not being able to pull the packer set at 4101' in the open hole, a string of 1 1/4" tubing was run with a pony packer set in the 3" tubing at 4080° and the well has produced thru the 1 1/4" tubing since that time. Due to the mechanical condition of this well and in the absence of any communication indicated on the bradenhead check, an exemption is requested on the temperature and pressure surveys.

(Company)

to the best of my knowledge.

Witnessed by.....

Approved:

(Name)

OIL CONSERVATION COMMISSION

unles

OCT