

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Los Cruces
Land Office *Alamogordo, New Mexico*
Lease No. *31029* Permit *#032233-A*
Unit _____
B. A. Dowers (Federal)

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. *A-12* is located *1900* ft. from *[N]* line and *600* ft. from *[E]* line of sec. *29*
N 1/4 of 31/4 of sec. 29 *100* *23* *Range* *Meridian*
Bowers *Los* *New Mexico*
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is *3656* ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested *5 1/2*" casing with 1000# pressure for 30 minutes at 6:45 PM *4-17-47*. Tested O.K.
Casing was cemented with 675 sacks of Lone Star cement. Plug was drilled on *4-17-47*.
Temperature survey found the top of cement behind the *5 1/2*" casing at 800'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company *Humble Oil & Refining Co.*
Address *Box 1600*
Midland, Texas
By *Ed Gallagher*
Title *Division Chief Clerk*