

## SUNDRY NOTICES AND REPORTS ON WELLS

NW/4	ell No. Anl2 is locate of SN/4 of Sec. 29. (Hi Sec. and Sec. No.) OWERS (Field)	ed <b>1980</b> ft. 18-3 (Twp.) Lea	from $\begin{cases} 1 \\ S \end{cases}$ line and	Texas d		,
NW/4	of SN/4 of Sec. 29	18-5 (Twp.)	from $\begin{bmatrix} \mathbf{M} \\ \mathbf{S} \end{bmatrix}$ line and <b>38-15</b>	d <u>660</u> ft. froi		,
	of SW/4 of Sec. 29	18 <b>S</b>	from $\begin{bmatrix} \mathbf{M} \\ \mathbf{S} \end{bmatrix}$ line and <b>38-15</b>	d <b>660</b> ft. froi		,
			from $\begin{cases} 1 \\ S \end{cases}$ line and			,
						,
			Midlan d.	Texas	April 7	10 <b>47</b>
	(INDICATE A	BOVE BY CHECK MA	ARK NATURE OF REPORT	, NOTICE, OR OTHER D	PATA)	
	IOTICE OF INTENTION TO ABANDON WE					1
	OTICE OF INTENTION TO PULL OR ALT					
N	OTICE OF INTENTION TO SHOOT OR AC				IMENT	1
	OTICE OF INTENTION TO RE-DRILL OR				ING OR REPAIR	1
, I	IOTICE OF INTENTION TO TEST WATER	SHUT-OFF			G CASING	i
	OTICE OF INTENTION TO CHANGE PLAI	NS			G OR ACIDIZING	
					4101-OFF	
	OTICE OF INTENTION TO DRILL		SUBSEQUENT	REPORT OF WATER S		X

The elevation of the derrick floor above sea level is <u>3656</u> ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested 8-5/8" casing with 1000# water pressure for 30 minutes on 4-5-47. Tested 0.K. Drilled plug at 12:45 P.M. 4-5-47.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Co.

Address Box 1600

Midland, Texas

	/ <b>/</b>	
$\cap$		
P		
by /	recett	
/ / / -		

THEFOLING

RNE

Title Ass't. Division Superin tendent

1-5

U. S. GOVERNMENT PRINTING OFFICE 16-8437-2